

RECONNAISSANCE & REFURBISHMENT SURVEY  
 ALL OF THE CORNERS OF THIS PROPERTY WERE FOUND AND REFURBISHED AS NOTED ON THIS PLAT. ALL OF THE LINES EXCEPT THE EAST LINE OF THE SW1/4-SW1/4 OF SECTION 12 WERE MARKED BY WHITE PAINTED LINES. ALL OF THE LINES WERE REMARKED WITH WHITE PAINT AND PINK RIBBON. THE ONLY ENCROACHMENT IS A FENCE LINE ALONG THE NORTH LINE AS SHOWN. THE BEARINGS, DISTANCES, AND AREAS WERE DETERMINED WITH HAND HELD GPS EQUIPMENT HAVING A POSITIONAL ACCURACY OF APPROXIMATELY 10 FEET. THIS METHOD WAS USED BECAUSE ALL OF THE MONUMENTS CONTROLLING THE LOCATION OF THIS PROPERTY WERE EXISTING AND HAVE BEEN ESTABLISHED FOR MORE THAN 40 YEARS. A MORE ACCURATE DETERMINATION OF THE AREA WOULD REQUIRE ACTUAL GROUND MEASUREMENTS BETWEEN THE CORNERS.


ELEVATION COUNTOUR LINES WERE TRACED FROM A USGS TOPOGRAPHIC MAP AND ARE PROVIDED AS A GENERAL LAYOUT ON THE LAND ONLY. EACH LINE REPRESENTS A CHANGE OF 20 FEET IN ELEVATION.

1 1/2" REBAR PIN	COMPUTED CORNER (NOT SET)
IRON PIPE	FENCE CORNER POST
ALUMINUM CAP	PINE TREE
RAILROAD SPIKE	HARDWOOD TREE
MONUMENT AS NOTED	FENCE LINE
1/2" REBAR PIN	PINK RIBBON DENOTES PROPERTY CORNERS AND LINES.
IRON PIPE	BASES OF BEARINGS.
ALUMINUM CAP	TRUE NORTH
RAILROAD SPIKE	
MONUMENT AS NOTED	



This plat represents my professional opinion as to location of the boundaries of the heretofore described piece of land as shown on this plat. It is based on the survey data furnished to me by the owner of the land. I have not conducted a physical survey of the land shown on this plat, and possession lines such as building encroachments or other encroachments, whether shown on this plat or not, may constitute a question of legal ownership. These questions should be resolved with the adjoining land owners before any changes are made to the boundaries of the land shown on this plat. I am not responsible for the accuracy of the plat, the reliability of the property for any particular purpose, or information that would be obtained by a title search.

SURVEY NOT VALID UNLESS




**Phillip Sloan & Assoc. Inc.**  
 230 Park 74, Mena, Ar. 71953  
 Arkansas 9254 947 ~ Oklahoma 9254 1204  
 FOR THE EXCLUSIVE USE OF:  
 RICHARD & ANNETTE ANDERSON  
 SEPTEMBER 8, 2003  
 STATE SURVEYOR'S RESPONSE NUMBER: 600-035-2014-01-130-07-0847  
 600-035-2014-01-130-07-0847  
 600-035-2014-01-130-07-0847

SET REBAR AT INTERSECTION OF FENCE LINE AND EXISTING WITNESS TREES 15' FROM CORNER 15' FROM CORNER 15' FROM CORNER 15'

SET REBAR AT EXISTING WITNESS TREES 15' FROM CORNER 15' FROM CORNER 15' FROM CORNER 15'

SET REBAR AT EXISTING WITNESS TREES 15' FROM CORNER 15' FROM CORNER 15' FROM CORNER 15'



Cabinet 7  
 Slide 536

TOWNSHIP 3 SOUTH ~ RANGE 29 WEST  
 POLK COUNTY ~ ARKANSAS  
 114 acres, more or less

2003 157  
 Recorded in the Above  
 Plat Book & Page  
 10-07-2003 10:20:46 AM  
 Sharon K. Simmons-Circuit & Ex-officio Rec  
 order  
 Polk County, AR

SET REBAR AT EXISTING WITNESS TREES 15' FROM CORNER 15' FROM CORNER 15' FROM CORNER 15'

SET REBAR AT EXISTING WITNESS TREES 15' FROM CORNER 15' FROM CORNER 15' FROM CORNER 15'